

Date: 12/7/2021
Doc. Revision: A
Revision Date:
ASA Model #: WVSXS43

Work Instruction: WVSXS43

Written By
R. Priddy
Approved By
Joe Caban

1. Pull parts per JDE work order
2. Build retail box.
3. Place monitor and camera in the retail box.
4. Label master carton with part number/barcode and with quantity.
5. Get first article inspection.

