

Date: 1/18/2022
Doc. Revision: A
Revision Date:
ASA Model #: WVSXS70

Work Instruction: WVSXS70

Written By
R. Priddy
Approved By
Joe Caban

1. Pull parts per JDE Work order
2. Build retail box
3. Place monitor and camera in retail box.
4. Label master carton with part number/barcode.
5. Get first article inspection.

