

PVOM74MMFFK (Field Fix Kit) Harness

3/19/18

Used to prevent VOM74MM from image inverting

NOTE: The Ignition (12V+ or ACC) power to the VOM74MM must be cut and the Relay/Capacitor module (Field Fix Harness) spliced in between.

