

Date: 10/26/2023
Doc. Revision: A
Revision Date:
ASA Model #: JHD22B

Work Instruction: JHD22B

Written By
R. Priddy
Approved By
Joe Caban

1. Pull parts per JDE work order.
2. Place harness in the original box
3. Place 2x4 Part number/bar code label on the outside of the box.
4. Get first article inspection.

