

MWR75 Troubleshooting Guide

Wired Remote Control not functioning

- Verify the remote is properly connected to the designated "wired remote" pigtail and not inadvertently connected to the Sirius Module or iPod pigtails.
- Verify remote is securely connected to radio directly and/or extension cable.
- Verify for there are no bent pins in connectors.
- Troubleshoot extension cable: try connecting directly to radio remote pigtail. If remote functions, the issue may be in the extension cable. Replace Extension Cable.
- If no change in issue replace the remote.