

## **AN150SR Troubleshooting Guide**

## **No Reception**

- With another radio, verify you have AM and FM radio stations with sufficient signal available in your area.
- Disconnect and reapply antenna coax cable to Motorola Antenna receptacle of stereo.
- Check for any breaks or kinks in the antenna base or coax cable. This may result in signal loss issues to stereo.
- Check for red power indicator. If no light, verify connections below:
  - Verify the Black wire is secure to a solid ground connection.
  - o Verify the Red Power wire is secure to a known good 12 volt DC lead.
- Replace with known good antenna.

## **Poor Reception**

- Relocate antenna to a higher position.
- Relocate if mounted to a window with metallic tint.
- Relocate if mounted under or behind fiberglass surfaces painted with metallic flake.
- Replace with known good antenna.