



WHPIR02 Troubleshooting Guide

Unit will not turn ON

- Verify the power switch is depressed and operating normally.
- Make sure batteries are properly inserted.
- Try new batteries.

No Sound

- Make sure headphones are ON.
- Make sure volume is turned up.
- Make sure IR transmitter is ON.
- Make sure you are within line-of-sight of IR transmitter.
- Make sure the headphones and IR transmitter are on the same channel.
- Confirm that the transmitter is installed and operating correctly.