



VA100 Troubleshooting Guide

Unit does not power ON.

- Verify power harness is connected to VA100.
- Check 12V+ on Red power wire.
- Check Ground.
- Check the vehicle's circuit for blown fuse.
- Inspect power harness for damage.

No Audio or Video signal.

- Check AV Cables for proper connection at both VA100 and source/destination components.
- Check AV cables for damage.
- Replace cables with new.
- Connect source output directly to component input to verify proper operation.